

BL1A T2 Issue

Y.-N. Rao

TRIUMF


Abstract: In this note we review the changes in the elevations of BL1A T2 target and its protect monitor over the last four years, with goal to pinpoint the primary misalignment that causes the reduction of TNF neutron flux.

4004 Wesbrook Mall, Vancouver, B.C. Canada V6T 2A3 Tel: 604 222-1047 Fax: 604 222-1074 www.triumf.ca

1 What is the issue?


Since 2013, the neutron flux as monitored by the TNF neutron monitor has been fluctuating during every year's production run. These fluctuations were partly related to the fact as to whether or not there were any targets installed in the TNF. When there were no targets installed in the TNF, the neutron flux was deemed to be close to 10 cps per μ A BL1 adjusted current. But when the TNF had a number of Moly targets installed, they reduced the proton energy producing fewer neutrons. This part is not the issue with argument. The issue is that the neutron flux had a reduction of about 20% even if there were no Moly targets installed in the TNF. This was evidently observable during the last 4 years particularly during the 2015 and 2016 production runs.

It was suspected that the proton beam was being forced off axis by the T2 Protect Monitor, as a result, a larger fraction of the beam was scraped by Collimator A which has a 1 cm radius entrance aperture. In terms of the REVMOC simulation result (see TRI-DNA-82-3), about 35% of the beam hitting T2 is normally lost on the Collimator A before entering TNF, as the beam size becomes largely blown up due to multiple scattering and nuclear scattering after passing through a 10 cm long T2 target (Be). The scattering angle is about 15 mrad (rms). If the beam enters the T2 target with an offset from Collimator A axis, then the acceptance angle of Collimator A is reduced, thus the furthest off-axis protons are scraped by the Collimator A, leading to the TNF neutron flux reduction. This is sketched below.



In order to pinpoint the primary misalignment that causes the neutron reduction, here I have to put together all the information of the last 4 years about the elevations of T2 Protect Monitor, T2 target, and Collimator A. According to Isaac Earle, the Collimator A has never been shifted intentionally since 2009, and its current elevation is supposed to be 1834.7 mm, measured from the collimator flange. Keep in mind that the magnitude of misalignment we are searching for here is merely about 2 to 3 mm, instead of in a centimeter range.

2 Year 2013




TNF Flux Rate 2013


There were no Moly targets installed in the TNF during the period from 2013-Jun-21 to 2013-Oct-11, over which the TNF neutron flux was reading as high as ~ 1000 counts (which corresponds to the 1 in the above plot) and was almost constant. And then from 2013-Oct-11 to 2013-Nov-28, there were 8 Moly targets installed in the TNF, thus the neutron flux dropped to ~ 650 counts (which corresponds to 0.65 in the plot). This drop was due to the energy reduction of proton beam passing through the Moly targets. Until 2013-Dec-04 when the Moly targets were removed, for a brief time the neutron rate came back to 1000 counts level.

Clearly, during each period, either with or without Moly targets installed in the TNF, the TNF neutron flux could increase or decrease for some reason. Nevertheless, it is making sense for the neutron user to consider the 1000 counts as their reference and desired value for the case without Moly targets.

During 2013, there were 2 targets used at T2, namely, from the beginning of May to Nov.21, and then from Nov.21 to the year end. Their elevations are shown below.



★ Note that during the 1st target period, the Protect Monitor was higher than the target by about 1838.0-1833.0=5.0 mm, and also HIGHER (not lower) than the Collimator A by about 1834.7-1833.0=1.7 mm.



★ During the 2nd target period, the Protect Monitor was higher than the target by about 1836.6-1833.0=3.6 mm, and also HIGHER (not lower) than the Collimator A by about 1834.7-1833.0=1.7 mm.

3 Year 2014

★ Over the weekend from 2014-Apr-25 to 2014-Apr-27, the T2 target was situated at position #4, taking 15μ A. The beam was kept centered vertically on the T2 Protect Monitor. See Eric Chapman's entries on the CycOps e-log.

2014-04-25 18:05:00 Summary: Remove 1AMT2 Detail: DT 2 mins	<u>Make Comment</u> - Eric Chapman
2014-04-25 18:14:00 Summary: Beam off to move T2 back to position 4 Detail: (No additional detail)	Make Comment
2014-04-25 18:17:00 Summary: Beam on to 2A and 1A Detail: (No additional detail)	Make Comment
2014-04-25 18:18:00 Summary: BL2A back up to 30uA, production resumes. Detail: (No additional detail)	<u>Make Comment</u> - Eric Chapman
2014-04-25 Summary: BL1A current limit set to 20uA. Issac Earle has requested we run 15uA down BL1A over the 18:18:07 weekend. On Monday T2 will be pulled for inspection. Detail: (No additional detail)	<u>Make</u> <u>Comment</u> - Eric Chapman
2014-04-25 19:31:40 Summary: Please keep beam vertically centered on the T2 protects. Detail: (No additional detail)	<u>Make</u> <u>Comment</u> Eric Chapman
2014-04-25 18:57:14 Summary: Retired Defeat 7011: MHESA B1 collective zone 02-001-001 Detail: Visual check of the area confirmed no personnel and all smoke detectors in place. Collective zone re-armed	<u>Make</u> <u>Comment</u> - David Bandiera

★ On the following Monday 2014-Apr-28, the T2 target was removed from the beamline and then transported to the hot cell for measurements. A clear spot was visible on the entrance and exit windows of the target. See Isaac's e-mail and photos that follow.

Subject: T2 Beam Spots From: Isaac Earle <iearle@triumf.ca> Date: 04/29/2014 05:15 PM To: Yuri Bylinski <bylinsky@triumf.ca>, Jamie Cessford <cessford@triumf.ca>, Thomas Planche <tplanche@triumf.ca>, Rick Baartman <krab@triumf.ca>, Yi-Nong Rao <raoyn@triumf.ca> CC: Scott Kellogg <kellogg@triumf.ca>, Ron Kuramoto <kur@triumf.ca>, Grant Minor <gminor@triumf.ca> Hello All, The T2-MK2 target was removed from the beam line yesterday afternoon and transported to the hot cell. A clear beam spot is visible on the entrance and exit windows of the target (photos below). The beam spot confirms where the beam was suspected to be and what the profile monitor was telling us (approximately 6mm high).
I performed horizontal and vertical measurements on the position 4 target and profile monitor, and also measured beam spot size/shape/location on the entrance and exit windows. These figures will be supplied to Ops once an elevation measurement has been taken of the new protect monitor.

The T2-MK2 target is ready to be returned to the beam line tomorrow morning.

Isaac







<u>T2-MK2</u> <u>BEAMSPOTS</u>

ENTRY












VIEWED FACING DOWNSTREAM








 \bigstar In terms of Isaac's photos and measurements, the beam spot centroid was upward displaced from the target centre-line by roughly 8.5/2=4.2 mm at entrance.

The displacement is roughly the same at the exit window. This indicates that the beam was pretty leveled through the target.

But remember that this beam was kept balanced up and down on the T2 Protect Monitor. Thus, this means that the target centre-line was misaligned by \sim 4.2 mm, too low relative to the Protect Monitor centre-line. This is consistent with the elevation info that Isaac provided, as shown next page, where the target was indicated to be (1838.2+1837.7)/2-1833.0=5.0 mm lower than the Protect Monitor. Note that the bigger number here means a lower elevation as the zero value is on the top.



It indicates that the target was lower than the protect monitor by (1838.2+1837.7)/2-1833.0=5.0 mm.

★ The target should be elevated by 4.2 mm to be flush with the Protect Monitor. But what actually happened was that the Protect Monitor was lowered by 6.8 mm, instead of the target being elevated. See the following Isaac's entry on the RH e-log of 2014-May-02.

RH-Meson Hall	Not logged in
🕅 🌒 🕨 🕅 List	
Message ID: 114	Entry time: Friday, May 02, 2014, 15:49
Author:	Isaac Earle
Category:	Repair
Туре:	Target 2
Specific:	Target
Subject:	T2 Protect Monitor Elevation Correction
assembly would be removed for inspection to visually confirm the suspected misalignment before increasing beam current. Since start-up, a maximum beam current of approximately 30 micro-amps had been used on the 10cm beryllium target in position 4 which previously had not seen beam. On Monday April 28th, the T2-MK2 target was transported from the beam line to the hot cell. The target assembly was measured to be 298mSv/hr at 0.5m. A clear beam spot was visible on the entrance and exit windows of the target approximately 6mm high of vertical center (photos attached). Target and profile monitor elevation measurements were conducted, and confirmed those previously taken on the target by Tom Lyth. This exercise confirmed that the position 4 target and profile monitor were aligned properly, and that misalignment of the protect monitor was the cause of the beam being high on the target. It was then decided that the protect monitor assembly would be removed and a new monitor cassette installed to remedy the problem. On Wednesday April 30th the T2-MK2 target was returned to the beam line and the protect monitor assembly was transported to the hot cell. A maximum field of 15mSv/hr at 0.5m from the protect monitor was measured. Elevation of the monitor cassette was checked, and was found to be 6.8mm above the elevation of the	
position 4 target. The monitor cassette was removed from the assembly. The cassette was approximately 100µSv/hr at 0.5m and 2mSv/hr on contact, with 200cpm measured from a swipe of the outside surfaces (not the inside plates). The cassette was returned to Probes Group for possible use in the future. A new monitor assembly was supplied by Scott Kellog on Friday morning with the 6.8mm adjustment. The monitor was installed on the protect monitor assembly. Elevation was checked and found to be within 0.5mm of the target elevation. After installation an electrical check was performed by Dave Cameron and Mike Russel.	
The protect monitor assembly is ready for installation in the beam line on Monday morning.	

★ In other words, after 2014-May-05, the protect monitor's elevation was 6.8 mm lower than that before 2014-Apr-28. This was seriously wrong; as a result of this, the beam appeared too high on the Protect Monitor, causing a lot of "T2 Protect Up" trips; also, the beam was too high at TNF, causing a lot of "TNF D-U" trips.

The correct adjustment should be elevating the target by 4.2 mm instead of lowering the Protect Monitor by 6.8 mm.

★ On 2014-May-14, the T2 target was returned to position #4 and 2 mm above the nominal position. See Grant Minor's entry on the RH e-log of 2014-May-14.

RH-Meson Ha	all Not logged in ELOC
	List
Message ID: 116	Entry time: Wednesday, May 14, 2014, 20:36
Author:	Grant Minor
Category:	Development
Туре:	Target 2
Specific:	Target
Culture to	
Subject:	Target exercised to position 0, then back to 2.0 mm above position 4
The T2 target was operations. The T2	exercised to position 0, then back to 2.0 mm above position 4 exercised to position 0 around 6:15pm so that the T2 profile monitor could be used by 2 water package was re-enabled when the target was in position 0, however this resulted e cooling package.
operations. The Ti in some trips of the	exercised to position 0 around 6:15pm so that the T2 profile monitor could be used by 2 water package was re-enabled when the target was in position 0, however this resulted
The T2 target was operations. The T2 in some trips of the Operations called a The target position	exercised to position 0 around 6:15pm so that the T2 profile monitor could be used by 2 water package was re-enabled when the target was in position 0, however this resulted e cooling package. around 7:45 to request return of the target to about 2mm above position 4. In was re-set so that the position reading fluctuated roughly between 2.7 and 1.6 mm hovering roughly around 2.0 mm), and so the potentiometer reading was hovering

But this 2 mm upward fine adjustment did not help, because the Protect Monitor was still too low, that is, the beam entered the target section too low. ★ The problem persisted, causing a lot of beam trips. We could not lower the beam position at T2 and TNF both to solve the trouble because we were limited by the beamline optics; the steerer SM11A,B was already maxed out and still wanted to go to higher setting.

There was no chance to re-align the T2 Protect Monitor before the 2014 Christmas shut-down. A provisional action taken was to lower the beam at TNF to make the TNF Protect Monitor balanced up and down and therefore to reduce the beam trips due to the TNF. We could not do this until we got a new power supply installed on the asymmetric quad Q16 to have more steering capability available for the steerer SM11A,B. We ended up getting chance to do the online adjustment on 2014-Oct-16. I had this well done within 15 minutes; it went straightforward. During that exercise, I did not try to lower the beam position at T2 at all.

★ But, 5 days later, that is, on the beam development shift of 2014-Oct-21, Yuri asked to lower the beam at T2 to make the T2 Protect Monitor look balanced. I warned him that this would be risky to the T2 target. Indeed, the beam appeared to be too lower on the target. Look at Isaac's messages and pictures in the following pages.


Note that Isaac's these info were produced on 2015-Feb-27, after the full 2014 running period.



Subject: Re: T2-MK2 Beam Spot Photographs From: Isaac Earle <iearle@triumf.ca> Date: 02/27/2015 01:03 PM To: bylinsky <bylinsky@triumf.ca> CC: Yi-Nong Rao <raoyn@triumf.ca>, Rick Baartman <krab@triumf.ca>, Thomas Planche <tplanche@triumf.ca>, Scott Kellogg <kellogg@triumf.ca>


Hi Yuri,

Here are plots of the entry and exit window beam spots with the outline of the beryllium material shown in blue. The grid spacing on the target window is 1mm. As you suspected, part of the beam is missing the target at the exit.



For the full 2014 running period the T2 target ladder was 2mm higher than the nominal position, to try to compensate for steering issues (the issue was corrected in October 2014, but the ladder position was not changed). The plot below shows the beam spots shifted up 2mm. This is what I would expect if the target ladder was set at the nominal position and beam tune was not changed. In the plot below the beam spot centers seem to be about 2.5mm below the target center, this indicates to me that the T2 protect is 2.5mm too high.

★ As a result of that, the TNF neutron flux dropped below 600 counts. This drop was very significant, starting from 2014-Oct-22, even until 2014-Nov-13 when the Moly targets were removed. See the following plot.




TNF Flux Rate 2014

★ In conclusion, from 2014-Oct-21 to the end of 2014, the T2 Protect Monitor which was sitting at elevation of 1833.0+6.8=1839.8 mm was lower than the Collimator A which was sitting at 1834.7 mm by 5.1 mm. This was responsible for the neutron flux getting significantly dropped below 600 counts.

The beam's incident angle seemed to be small, as the centroid of beam spot on the entrance window was at an elevation of $\sim (1838.2-2.0+4.0)=1840.2 \text{ mm}$ (where the 1838.2 mm was the nominal position of target centre-line, the 2 mm was the upward fine adjustment of the target ladder during the full 2014 running period, whereas the 4 mm was the downward displacement of the beam spot centroid w.r.t. the target centre-line.). This was about the same elevation as the Protect Monitor's centre-line of 1839.8 mm. **\star** On 2015-Apr-23 (during the winter shutdown), Isaac took photos of the old Protect Monitor. See his e-log entry and photos below.

RH-Meson Hall	Not logged in	
🕅 🌒 🕨 🕅 List		
Message ID: 154 En	try time: Thursday, April 23, 2015, 13:40	
Author:	Isaac Earle	
Category:	Development	
Туре:	Target 2	
Specific:	Other	
Subject:	T2 Protect Monitor Elevation Adjustment	
 above and 5mm south of plate centers (cause unknown, and no matching mark on entrance side) Old monitor cassette removed, new one installed. New elevation 1836.1mm (2.9mm upward shift - 3.0mm was requested) Electrical check performed by Probes Group on April 22 - They reported that it looks normal T2 Protect Monitor returned to the beamline April 22 in the evening. Cables plugged in and flange bolts installed Vacuum pumped down normally on April 23 in the morning Probes group repeated the electrical check after installation from the 1A mezzanine - They reported that it looks normal The old monitor cassette will be left in the hot cell for possible future use 		
Attachment 1:	Old_T2_Protect_Monitor_(removed_Apr_22_2015)Entry_Side.jpg 222 kB Hide Hide all	

Photos of the Protect Monitor used for the 2014 production run.




Clearly, there were 2 heat marks noticed on the exit side: one was significantly above the plate centre, the other was flush with the gap.

4 Year 2015

★ On 2015-Apr-23, a new Protect Monitor was installed with its elevation upward adjusted by 2.9 mm relative to the old one used over the previous year from 2014-May-05 to 2014 Christmas shutdown.

RH-Meson Hall	Not logged in
🕅 🌒 🕨 🕅 List	
Message ID: 154 Ent	try time: Thursday, April 23, 2015, 13:40
Author:	Isaac Earle
Category:	Development
Туре:	Target 2
Specific:	Other
Subject:	T2 Protect Monitor Elevation Adjustment
 above and 5mm south of plate centers (cause unknown, and no matching mark on entrance side) Old monitor cassette removed, new one installed. New elevation 1836.1mm (2.9mm upward shift - 3.0mm was requested) Electrical check performed by Probes Group on April 22 - They reported that it looks normal T2 Protect Monitor returned to the beamline April 22 in the evening. Cables plugged in and flange bolts installed Vacuum pumped down normally on April 23 in the morning Probes group repeated the electrical check after installation from the 1A mezzanine - They reported that it looks normal The old monitor cassette will be left in the hot cell for possible future use 	
Attachment 1:	Old_T2_Protect_Monitor_(removed_Apr_22_2015)Entry_Side.jpg 222 kB Hide Hide all
Attachment 2:	Old_T2_Protect_Monitor_(removed_Apr_22_2015)Exit_Side.jpg 229 kB

Also, look at the following sheet that Isaac documented about the "T2-MK2 ELEVATION".




It indicates that the Protect Monitor was higher than the target by (1838.7+1837.9)/2-1836.1=2.2 mm.

★ This newly installed Protect Monitor ran under these conditions until 2015-Sept-21 mini shutdown started. Coming out of this shutdown, it had been reading wrong and becoming worse and worse over time.

Thus, on 2015-Oct-05 a decision was made to uncover and remove the T2 Protect Monitor for inspection. See Isaac's e-log entry of 2015-Oct-09 and pictures below for details.

-			
RH-Meson Hall	Not logged in		
🕅 🌒 🕨 🕅 List			
Message ID: 179 En	try time: Friday, October 09, 2015, 14:56		
Author:	Isaac Earle		
Category:	Repair		
Туре:	Target 2		
Specific:	Other		
Subject:	T2 Protect Monitor Replacement		
	cision was made to uncover and remove the T2 Protect Monitor due to faulty readings. The ng strangely since the September shutdown, and had been getting worse over time.		
	ver T2 starting Monday afternoon. It is necessary to remove the narrow 12' block and two 6' g block in order to fit the flask frame in for protect monitor removal		
	- The monitor was moved to the hot cell by 7pm on Monday. Pierre was operating the crane and there were no issues with the move. (monitor measured 15mSv/hr at 0.5m)		
Oct 6:			
- Monitor inspected: a thin piece of foil was found jammed into the entrance side of the monitor (see photos) & a heat or burn mark was seen on the exit side above and to the south of the plate gap. It is suspected that this material traveled down the beamline at high speed when there was a vacuum burst during the September shutdown. In light of this information it was decided to remove the T2 target and T1 target as well (see following e-logs)			
- Monitor elevation measured: 1835.8mm (april 2015 measurement was 1836.1> ok)			
- <u>Old monitor cassette removed, new one installed</u> . Elevation checked: 1832.2mm - did not match, removed, decontaminated, and returned to Probes for adjustment			
- Adjusted monitor installed, elevation checked: 1835.8mm> ok			
- Electrical check done by Probes group at hot cell: found left plate shorted to ground			
- Cassette removed, decontaminated, and repaired by Probes Group			
- Cassette reinstalled, and electrical check repeated> ok			
Oct 7:			
- Monitor elevation re-ch	- Monitor elevation re-checked: 1836.2mm> ok		
- T2 protect returned to beamline, bolts installed, cables connected			

A thin piece of foil was found jammed into the entrance side of the monitor :





And a heat or burn mark was seen on the exit side above and to the south of the plate gap. ==>

To replace the damaged protect monitor, a new one was put in.






 \bigstar And then, Isaac checked the T2 target beam spots on the entrance and exit windows. See following entry and photos.

RH-Meson Hall	Not logged in
🕅 🌒 🕨 🕅 List	
Message ID: 180 Er	ntry time: Friday, October 09, 2015, 15:18
Author:	Isaac Earle
Category:	Repair
Туре:	Target 2
Specific:	Target
Subject:	T2-MK2 Check at Hot Cell and Motor Drive Cable Replacement
	as uncovered for T2 Protect repair (see previous e-log), it was decided that the T2 target should be address issues discovered last week with target ladder movement (see e-log #175)
- T2-MK2 target was mo 896mSv/hr at 0.5m)	ved from the beamline to the hot cell after the T2 protect was reinstalled (the target measured
	ed in the hot cell: profile monitor looked normal, <u>two beam spots (one higher, one lower) were</u> we window (see photos), the spot on the exit window was low but not quite touching the weld
- T2 profile monitor was	checked by probes group at the hot cell> ok
	checked by cycling through all target positions twice using the portable control box. This revealed th Ily functioning properly and the fault lies elsewhere
ground. Attempts to fix	cable from 1A racks to beamline with Dave Cameron. Found Pin B has 190kOhm short to building the cable at both ends were unsuccessful and spare wires in the bundle could not be used because able at an unknown location and use of wire colours in both sections is inconsistent
	elevation: 1839.0mm with potentiometer at 16.19kOhms. This is consistent with previous mm. This confirms that pot, motor, and drivetrain for ladder movement are all ok.
Oct 8:	
	ble for target motor drive (already had on hand for T1/T2 controls upgrade in 2016 shutdown). The TR-DRV. It was first tested at the hot cell and then installed by Doug and Ron
- <u>The T2-MK2 target was returned to the beamline</u> . A camera and monitor setup was used to watch the target entering the hole remotely which greatly reduced dose (inserting the target requires multiple iterations to get alignment correct, so dose i typically higher than when removing devices from the monolith)	
- T2 profile and protect monitors checked by Probes Group from the mezannine> both ok	
- T2 profile and protect	

Photographs were taken on 2015-Oct-07 of beam spot on the T2 entrance window : and beam spot on the T2 exit window:

 \bigstar Clearly, there were 2 spots visible on the target, but shifted up and down.


\star On 2016-Apr-11 (during the winter shutdown), the T2-MK2 target was photographed as well. Shown below.



Similar to the pictures of Oct. 2015, overall the spots were low on the target.

★ Noticed that during the period from 2015-May-12 (when 1A just started up to take beam) to 2015-Sept-20 (when the mini shut-down started), the TNF neutron flux overwhelmingly exceeded 800 counts, and even reached 900 over 3 periods, namely, from May 26 to Jun.24, from Jul.30 to Aug.18, and from Sept.4 to Sept.20.

Coming out of the repair, the neutron flux had around 800 counts, not so bad. But, from Nov.12 to Dec.8, it dropped below 800.



TNF Flux Rate 2015

(c) ops, 2016/May/29

time (year)

★ These fluctuations in the neutron flux were just related to the fact that the beam spot was shifted up and down on the target, because there were no Moly targets installed at TNF during 2015 production run.

 \bigstar Here we take the elevations of the T2 Protect Monitor and T2 target during the 2015 production run as a reference, which were:

1836.2 mm for the Protect Monitor centre-line,


 $(1838.7+1839.0)/2=1838.9 \,\mathrm{mm}$ for the T2 target entrance,

1834.7 mm for the Collimator A.

Note that the Protect Monitor was higher than the target by about 2.7 mm, but still LOWER (not higher) than the Collimator A by about 1.5 mm.

During this period of production run (from 2015-Oct-10 to the year end), the beam was kept balanced on the Protect Monitor vertically. This suggests that the beam was entering the target section with an angle. This angle was roughly 2.7 mm/(32-5) cm=10.0 mrad downward.


5 Year 2016



Noticed that the Protect Monitor was higher than the target Position #4 by (1838.7+1837.9)/2-1836.2=2.1 mm, and higher than the Position #1 by (1839.7+1839.6)/2-1836.2=3.5 mm, but still LOWER (not higher) than Collimator A by 1836.2-1834.7=1.5 mm. ★ On 2016-May-13, the T2-MK2 target Position #4 started to take beam. From the start to June 1, the neutron flux was constantly reading as low as 600 counts.

★ On June 2, Eric Chapman intentionally mis-steered the beam as requested to provide more counts to TNF. Eric had to let the beam position be high vertically and be left horizontally on the T2 Protect Monitor in order to increase the TNF counts up to 800.

Should be pointed out that during the 2016 production run there were no Moly targets installed at TNF.



TNF Flux Rate 2016


(c) ops, 2017/Mar/01



★ On 2016-June-15, the T2-MK2 target was moved to Position #1 from the previous Position #4, because the Position #4 target had reached the maximum beam time. This new target, namely, the Position #1 target, was used for the remainder of the 2016 running period. See Isaac's e-log below.

RH-Meson Hall	Not logged in
🕅 🌗 🕨 🕅 List	
Message ID: 201 En	itry time: Wednesday, June 15, 2016, 11:00
Author:	Isaac Earle
Category:	Standard Operation
Туре:	Target 2
Specific:	Target
Subject:	T2-MK2 Target Moved to Position #1
Position #4 on the T2-MK2 target has now reached the maximum beam time. The target was moved to Position #1 at the nominal elevation. This target should be used for the remainder of the 2016 running period.	

But, from 2016-June-15 to the end of 2016, the TNF neutron flux constantly stayed below 800 counts. During this period, the beam was kept balanced vertically and to the right horizontally on the T2 Protect Monitor.



(c) ops, 2017/Mar/01

Time (Year)


★ On 2017-Jan-09 (during the winter shutdown), the T2-MK2 target in Position #1 was photographed and measured for the spots, shown below.

Message ID: 213	Entry time: Thursday, January 12, 2017, 09:21
Author:	Isaac Earle
Category:	Standard Operation
Type:	Target 2
Specific:	Target
Subject:	T2-MK2 Position 1 Beam Spot

The beam spot on the 10cm beryllium target in Position 1 on T2-MK2 (Target ID: "OCT.06#3") was measured and photographed vesterday. A fairly well centered spot was measured to be approximately 4.6mm wide x 5.2mm tall on the entrance window and 5.7mm wide x 7.6mm tall on the exit window using the Nikon micrometer level. This target first saw beam on June 16, 2016.

A PDF scan of the beam spot measurements and photographs of the beam spots are attached.





 \bigstar Use Isaac's figures as a rough estimate, vertically the beam centroid was at

(1.8+3.4)/2 -3.4=-0.8 mm at entrance,

and

$$(2.3+5.3)/2$$
 -5.3=-1.5 mm at exit.

The offset was about 0.7 mm downward, suggesting that the beam was angling downward by 7 mrad onto the T2 target as the target was 10 cm long. At least in terms of the angling direction being downward, this angle was consistent with the elevation difference between the Protect Monitor and the target, which was (3.5+0.8)mm/(32-5)cm=16 mrad.

6 Conclusions

★ Over the last 3 years from the beginning of 2014 to the end of 2016, the T2 Protect Monitor's elevation has been lower than that of Collimator A by about 1.5 to 5.1 mm.

★ There were evidences showing that the beam was angling downward onto the T2 target. This angle was roughly 10 mrad. This angle could explain the 2 observations consistently: one was that the beam spot was seen to be higher on the target entrance window than on the exit window; the other was that when the beam was kept balanced up and down on the Protect Monitor, it was seen to be more or less centered on the target entrance window. But remember that the Protect Monitor was ~ 3 mm higher than the target which is at ~ 30 cm downstream from the Protect Monitor.

When the beam was angling onto the target, the TNF neutron flux could hardly reach 800 counts level, no matter it was centered on the target entrance window or shifted downward. The downward shift produced even less (significantly less!) neutron counts.

★ Since we have no real-time measurements about the position and incident angle of beam entering the target, and bear in mind that the beam just wanted to be higher on the Protect Monitor to produce > 800 neutron counts, we've decided to elevate both the Protect Monitor and the target by 3 mm from where they are. Specifically, they shall be set to the following elevations:

T2 Protect Monitor centre-line: 1833.5 mm, w.r.t. the T2 target flange.

T2 target centre-line: 1836.5 mm, w.r.t. the T2 target flange.

The T2 profile monitor shall be set to the same elevation as the T2 target centre-line.

The current elevation of Collimator A is at 1834.7 mm, w.r.t the T2 target flange.

We're going to try with these new settings to recover the neutron flux of >800 counts.

Even though OPS might tune the beamline to get, by chance, the beam more leveled through the target section and the Collimator A that follows, that would be even easier for the beam to pass through the Collimator A, because the Collimator A has a full aperture of 20.0 mm at minimum which is way larger than the remaining offset of 1.2 mm vertically between the Collimator A and the T2 Protect Monitor.

7 Acknowledgement

The author thanks Isaac Earle for providing the target elevation info, and appreciates Kathleen Genge for making the nice plots of neutron rates with notation.